




## Appendix O Environmental Features Mapping and Photographs


















































**Photograph 1:** Open field at Property 80 with meadow in background (Mayfield and Chinguacousy Road intersection) (June 14, 2024).



**Photograph 3:** Wetland polygon at evening calling amphibian survey station #2 east of Creditview Road, facing northeast (June 14, 2024).



**Photograph 2:** Planted soybean field at 12101 Creditview Road. Many agricultural fields in study area are either soybean, corn or were fallow during the field program (June 14, 2024).



**Photograph 4:** Woodland F at 12455 Creditview Road, facing northeast (June 14, 2024).





**Photograph 5:** North end of Woodland B at 12300 Mississauga Road, facing south (June 14, 2024).



**Photograph 7:** Open Aquatic ELC polygon (pond) at 12602 Chinguacousy Road; a male Little Blue Heron was observed (June 12, 2024).



**Photograph 6:** Meadow ELC polygon occupied by Eastern Meadowlark and Bobolink at 12602 Chinguacousy Road (June 14, 2024).



**Photograph 8:** Territorial male Bobolink at 12472 Chinguacousy Road (suspected to be paired) (June 14, 2024).





**Photograph 9**: Extent of leaf off conditions in Woodland B during bat snag survey (May 3, 2024).



**Photograph 11:** House likely requiring a future bat exit survey at 12455 Creditview Road (April 9, 2024).



**Photograph 10:** Acoustic monitor pole and microphone on western edge of Woodland F (May 31, 2024).



**Photograph 12:** Barn likely requiring a future bat exit survey at 12300 Mississauga Road (April 9, 2024).





**Photograph 13**: Alloa Drain, looking upstream (southwest) from culvert inlet at Chinguacousy Road (May 15-16, 2024).



**Photograph 15:** Alloa Drain, looking downstream from Fraser Drain confluence – upstream segment of feature (May 15-16, 2024).



**Photograph 14:** Alloa Drain, looking downstream at channel near mid-point of study area, east of Creditview Road (May 15-16, 2024).



**Photograph 16:** Tributary #2, looking downstream (east) at dense vegetation along channel (May 15-16, 2024).





**Photograph 17**: Tributary #3, looking upstream (west) at indirect fish habitat segment of feature (May 15-16, 2024).



**Photograph 19:** Tributary #5, looking upslope (west), no defined channel or substrate sorting, dense terrestrial vegetation (May 15-16, 2024).



**Photograph 18:** Tributary #4, looking upstream (northwest) at poorly defined flow path through agricultural field (May 15-16, 2024).



**Photograph 20:** Tributary #7, looking upstream near southern limits of feature (May 15-16, 2024).





**Photograph 21**: Tributary #9, lowland area in forest with no defined banks or substrate sorting (May 15-16, 2024).



**Photograph 23:** Lyons Drain, upstream segment in forested lands (May 15-16, 2024).



**Photograph 22:** Lyons Drain, downstream segment on east side of Creditview Road (May 15-16, 2024).



**Photograph 24:** Fraser Drain, looking downstream from mid-point of feature (May 15-16, 2024).

